



- Basic Knowledge / SOP
- Workmanship Technique
- Problem
- Improvement

OPL- CRWN-038

Description: Replacing damaged rubber seal side lift up windows

1 Remove damaged seal



2 Remove residue adhesive with alcohol



3 Apply 3M primer to surface in preparation for new seal C5-55-6074



4 Remove protective tape from seal and stick seal to window frame moulding it around the corners of the frame.



Date : 24.05.2016